



Year: 2019-2020
Category: Motorcycles
Sub-Category: Standard
Model: Monkey[®]

NHTSA Recall Number: 19E-071

Campaign Description QA: Honda Genuine Accessory Rear Carrier
MFR Campaign ID: KK5
Recall Date: 10/17/2019

Summary

American Honda Motor Co., Inc. (Honda) is recalling all genuine accessory rear carriers that may have been installed on certain 2019 and 2020 Monkey motorcycles. The carrying capacity for the rear carrier is lower than specification, therefore, the rear carrier can break when carrying less than its stated maximum capacity.

Safety Risk

If the rear carrier breaks while the motorcycle is in motion, the rear carrier can interfere with the motorcycle or fall into traffic, increasing the risk of a crash.

Remedy

Please call any authorized Honda Powersports dealer and make an appointment to have the rear carrier uninstalled and any related mounting hardware replaced for free. Since no replacement rear carrier will be available, a refund will be issued in exchange for the rear carrier. For additional questions or to get help locating a dealer, owners may contact Honda Powersports customer service at 1-866-784-1870.